

# OFFICE OF EXECUTIVE ENGINEER

PWD (B/R) NORTH BASTAR DIVISION NO 01, JAGDALPUR

MEMO NO 4003 T/S


JAGDALPUR DATED 12/07/2024


## BUILDING FITNESS CERTIFICATE


1. Inspector Name :- Nitesh Jaiswal (Sub Engineer P.W.D)
2. Building Name :- Deepti Convent Higher Secondary School Dharampura, Aghanpur,
3. Building Permit No. :- \_\_\_\_\_
4. Address :- Near MPM Hospital, Aghanpur, Jagdalpur
5. Description :- .....
6. Owner :- Aradhana Society, Jagdalpur
7. Period for which the Certificate is Issued :- 2024-25
8. Nature of defects, if any
  - a. Foundation & Building :- Defect Not Found
  - b. Superstructure :- Defect Not Found
  - c. Doors & Windows :- Defect Not Found
  - d. Wood Work :- Defect Not Found
  - e. Flooring :- Defect Not Found
  - f. Miscellaneous (Crack, etc) :- Minor hair Crack, its Repairable
9. Any major defects noticed which will render the building unsafe in any manner  
Seen my major defect :- Minor Deffect : Extension of bars Provided in Stairs in Top Floor Should be Bend Towards Upside , so that no Accident should happen in Future.
10. Whether maintenance works have been done properly :- Yes
11. Whether the structure is sound or not for occupation :- Yes (Sound)

## CERTIFICATE

It is certified that the building was inspected by me on 12/07/2024 and found to be fit/until for occupancy, for the period of 2024-25 For the reasons stated above.

  
Sub Engineer

  
Sub Divisional Officer  
P.W.D.(B/R) Sub Div.- No.-2  
Jagdalpur

  
Executive Engineer  
P.W.D.(B/R) North Bastar Div. No.-1  
Jagdalpur