## OFFICE OF EXECUTIVE ENGINEER

# PWD (B/R) NORTH BASTAR DIVISION NO 01, JAGDALPUR MEMO NO 3 2 7/S JAGDALPUR DATED 13/06/2025

#### BUILDING FITNESS CERTIFICATE

	BUILDING FITNESS CERTIFICATE									
1.	Inspector Name	5 <del>4</del>	Nitesh Jaiswal (Sub Engineer P.W.D)							
2.	Building Name	:-	Deepti Convent Higher Secondary							
			School Dharampura_Aghanpur,							
3.	Building Permit No.	i-								
4.	Address	1723	Near MPM Hospital, Aghanpur,							
			Jagdalpur							
5.	Description	Sec.								
6.	Owner	1-	Aradhana Society, Jagdalpur							
7.	Period for which the Certificate is									
	Issued	:-	2025-26							
8.	Nature of defects, if any									
2	. Foundation & Building	: •	Defect Not Founded							
ł	o. Superstructure	1 -	Defect Not Founded							
(	Doors & Windows	: •	Defect Not Founded							
(	l. Wood Work	) =	Defect Not Founded							
6	e, Flooring	1-	Defect Not Founded							
f	Miscellaneous (Crack, etc)	1	Minor hair Crack, its Repairable							
9.	Any major defects noticed which will									
	render the building unsafe in any manner									
	Seen my major defect	1 -								
10	. Whether maintenance works have been									
	done properly	<u>.</u> -	Yes							
11	. Whether the structure is sound or not									
	for occupation	‡ <del>-</del> -	Yes (Sound)							

#### CERTIFICATE

It is certified that the building was inspected by me on  $\frac{13}{06}/2024$  and found to be fit/until for occupancy, for the period of  $\frac{2025-26}{2025-26}$  For the reasons stated above.

Sub Engineer

Sub Divisional Officer P.W.D.(B/R) Sub Div.- No.-2 Jagdalpur Executive Engineer
P.W.D.(B/R) North Bastar Div. No.-1
Jagdalpur

### BUILDING SAFETY CERTIFICATE

TA: T	_
DVI.	•
1.94	

Dated: 18/06/2025

It is Certified that the existing building <u>Deepti Convent Higher Secondary School</u> (name of the building premises) at <u>Aghanpur Dharampura Jagdalpur Bastar</u> (address) is having block(s)/ Floor(s) as per detail below:

Detail of Block(s) in School	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	02	02	03			

The building is owned/ occupied by <u>Aradhna Society</u> (name) of the Institution) have complied with the building safety requirements in accordance with National Building code Rules, and Verified by the officers concerned of <u>Public Works Department North Bastar Div no 01, Jagdalpur</u> (Name of Department/ Govt.) on <u>13/06/2025</u> (date of inspection) in the presence of <u>R.K Batra</u> (name and addresses of the Manager / Secretary or his representative) and that the building/ premises is fit for occupancy for running school with effect from 13/06/2025 for a period of 1 Years in accordance with rule and subject to compliance of the specific conditions as appended.

by	
e. In case of block is more than	n six use separate sheet
Signature with seal	Executive Engineer  PWD. (B&R) North Bastar Div. No -)  AGDALPUR
	e. In case of block is more than

Name : Rek. BATRA

Designation : Executive Engineer

Name & Address of P. W.D. North Bastar

Div No.1, Jaydalpur

Department/ Office

65

2.